

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CV492
ENE
1/2-1
0.762 mi.
4024 ft.

CURTIS RESIDENCE
2620 OCEAN PARKWAY
BROOKLYN, NY

NY LTANKS S106971433
N/A

Site 1 of 3 in cluster CV

Relative:
Higher

Actual:
9 ft.

LTANKS:

Name: CURTIS RESIDENCE
Address: 2620 OCEAN PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0408238 / 2005-04-18
Facility ID: 0408238
Site ID: 332909
Spill Date: 2004-10-26
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2004-10-26
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-10-26
Spill Record Last Update: 2005-04-18
Spiller Name: JORDON CURTIS
Spiller Company: CURTIS RESIDENCE
Spiller Address: 2620 OCEAN PARKWAY
Spiller County: 001
Spiller Contact: JORDON CURTIS
Spiller Phone: (718) 788-7900
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 268131
DEC Memo: "tff letter sent 10/25 3/2/2005 Sangesland reviewed a submittal from

Remarks:

Jordan at TKR Properties (718-788-7900) Report shows Eastmond made repairs to the tank on 11/5/2004 (rewelded a patch), and then installed a new vent line & new stick line on 11/8/2004. Finally installed new suction & return lines on 11/9/2004. The whole system (7500gal tank & lines) was retested on Nov 11, 2004 and passed. Sangesland requested written statement from Eastmond saying they did not find any contamination during their work on site. 4/18/2005 Sangesland reviewed a letter submitted by Isaac Mungra of Eastmond & Sons saying that No evidence of oil stains or contamination was observed during the replacement of the vent, stick, suction and return lines . The letter also restates all of the work outlined above. Spill Closed - No Further Action Required"
"RECOMMEND: EMPTY TANK AND DO AN IOSLATION TEST:"

All TTF:

Facility ID: 0408238
Spill Number: 0408238
Spill Tank Test: 1548282

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Site ID: 332909
Tank Number: Not reported
Tank Size: 7500
Material: 0003
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:

Site ID: 332909
Operable Unit ID: 1095114
Operable Unit: 01
Material ID: 575240
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported